

**Job Site Repair LLC**  
 12015 Brockton Ln N  
 Maple Grove, MN. 55369  
 Phone: 763-428-8891 Fax: 866-454-6909

**INVOICE**

**225459**

**INVOICE**

Ref # : 401959

Printed Date: 12/31/2022

Work Completed: 12/29/2022

**Midwest Deliveries, Inc. - Ryan Brunette**  
 489 Omaha Road  
 Hudson, WI 54016  
 Cellular 651-775-7381

2010 Freightliner - Van Chassis - MT-55 - Cummins ISB6.7 CM2250 6 C  
 Lic # : YCB1415 Odometer In : 158112  
 Unit # : 401959  
 VIN # : 4UZAARDU5 ACAN9112

Part Description	Qty	Sale	Ext	Labor Description	Ext
Position sensor	1.000	81.55	81.55	Work Requested: Keeps shutting down	n/c
Job Supplies			15.630	Diagnostics	50.00
				Engine/transmission/ABS/vehicle Diagnostics	
				Labor	262.50
				Scan for engine codes, camshaft position sensor failure present.	
				Replace sensor and run forced regeneration. Run vehicle for 6 hours without shutting down.	
				<b>[ Recommendations ]</b>	
				FAI due by 4/30/2023	

Org. Estimate 415.69      Revisions 0.00      Current Estimate 415.69

<b>Labor:</b>	<b>312.50</b>
<b>Parts:</b>	<b>97.18</b>
<b>SubTotal:</b>	<b>409.68</b>
<b>Tax:</b>	<b>6.01</b>
<b>Total:</b>	<b>415.69</b>
<b>Bal Due:</b>	<b>\$415.69</b>

[ Payments - ]

Vehicle Received: 12/29/2022

Customer Number : 61

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: [www.jobsiterepair.com](http://www.jobsiterepair.com)

Email Address: [jeff@jobsiterepair.com](mailto:jeff@jobsiterepair.com)