

**Job Site Repair LLC**  
 12015 Brockton Ln N  
 Maple Grove, MN. 55369  
 Phone: 763-428-8891 Fax: 866-454-6909

**INVOICE**

**231801**

**INVOICE**

Ref # : 403152

Printed Date: 05/12/2023

Work Completed: 05/11/2023

**AZAL, Inc. - Ali Aldera**  
 7317 W Franklin Ave.  
 St. Louis Park, MN 55426  
 Office 612-803-1511 Ali Aldera  
 Cellular 651-666-3354 Ryan Fritz

2017 Freightliner - Van Chassis - MT-55 - Cummins ISB6.7 CM2350 6 ( )  
 Lic # : YBU2821 Odometer In : 138572  
 Unit # : 403152  
 VIN # : 4UZAARDU6 HCJF5379

Part Description	Qty	Sale	Ext	Labor Description	Ext
Sensor NOX	1.000	769.58	769.58	Work Requested: CEL is on	n/c
ABS Motor	1.000	1,283.67	1,283.67	Diagnostics	50.00
Job Supplies			17.630	Engine/transmission/ABS/vehicle Diagnostics	
				Labor	137.50
				Scan for codes, engine code for failed NOX sensor, order parts. ABS light was on for failing ABS pump motor, advise owner and order parts. Replace NOX sensor, run forced regeneration, passed. Clear codes.	
				Labor	165.00
				Remove ABS pump motor, pins corroded, clean pins and replace motor. ABS valve still good to run. Replace motor, clear codes and test drive, no warning light returning after repairs.	
				<b>[ Recommendations ]</b>	
				PM due by 9/9/2023 or 141,646 miles to extend the life of your vehicle.	
				FAI due by 1/31/2024	
				Maintenance interval due 3/27/2023 to your vehicle.	

Org. Estimate 2,577.89 Revisions 0.00 Current Estimate 2,577.89

<b>Labor:</b>	<b>352.50</b>
<b>Parts:</b>	<b>2,070.88</b>
<b>SubTotal:</b>	<b>2,423.38</b>
<b>Tax:</b>	<b>154.51</b>
<b>Total:</b>	<b>2,577.89</b>
<b>Bal Due:</b>	<b>\$2,577.89</b>

[ Payments - ]

Vehicle Received: 5/11/2023

Customer Number : 4

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: [www.jobsiterepair.com](http://www.jobsiterepair.com)

Email Address: [jeff@jobsiterepair.com](mailto:jeff@jobsiterepair.com)