

**Job Site Repair LLC**

12015 Brockton Ln N

Maple Grove, MN. 55369

Phone: 763-428-8891 Fax: 866-454-6909

**INVOICE****231976****INVOICE**

Ref #: 435120

Printed Date: 05/23/2023

Work Completed: 05/22/2023

**Lake View Delivery, Inc. - Nathan Wegener**

2812 Maryland Ave. S.

Minneapolis, MN 55426

Cellular 612-817-6566

2013 Freightliner - Van Chassis - MT-55 - Cummins ISB6.7 CM2250 6 (

Lic #: YBY4084

Odometer In : 156500

Unit #: 435120

VIN #: 4UZAARDU6 DCFJ5302

Part Description	Qty	Sale	Ext	Labor Description	Ext
Bearing race wheel	2.000	30.03	60.06	Work Requested: Shakes when braking	n/c
Bearing wheel	2.000	78.88	157.76	Labor	550.00
Race wheel	2.000	18.28	36.56	Test drive vehicle and confirm shaking while braking on front end.	
Bearing wheel	2.000	25.05	50.10	Remove wheels, found front rotors warped, and too much freeplay in front hubs. Remove hub assemblies, clean up hub surfaces and pack new bearings with grease. Reassemble both sides with new bearings, races, rotors and wheel seals. Replace front brake pads, existing were at 4 MM thick. Test drive with no shaking while braking noted after repairs.	
RTV Black	1.000	16.14	16.14		
Rotor	2.000	200.37	400.74		
Seal	2.000	37.15	74.30		
Brake Disc Pads	1.000	72.75	72.75		
Hood shock 20 1/2in	1.000	33.66	33.66	Labor	27.50
Job Supplies			28.880	Replace broken non- locking hood shock	
				<b>[ Recommendations ]</b>	
				FAI due by 6/30/2023	
				PM due by 9/8/2023 or 159,173 miles to extend the life of your vehicle.	
				Maintenance interval due 6/8/2023 to your vehicle.	

Org. Estimate 1,576.33 Revisions 0.00 Current Estimate 1,576.33

<b>Labor:</b>	<b>577.50</b>
<b>Parts:</b>	<b>930.95</b>
<b>SubTotal:</b>	<b>1,508.45</b>
<b>Tax:</b>	<b>67.88</b>
<b>Total:</b>	<b>1,576.33</b>
<b>Bal Due:</b>	<b>\$1,576.33</b>

[ Payments - ]

Vehicle Received: 5/22/2023

Customer Number : 79

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: [www.jobsiterepair.com](http://www.jobsiterepair.com)Email Address: [jeff@jobsiterepair.com](mailto:jeff@jobsiterepair.com)