Job Site Repair LLC

12015 Brockton Ln N Maple Grove, MN. 55369

Phone: 763-428-8891 Fax: 866-454-6909

INVOICE

231970

Odometer In: 42871

INVOICE Printed Date: 05/23/2023 Work Completed: 05/22/2023 Ref #: 436038

Ryker, Inc. - Ryan Husband

2021 Ford - F59/F53 Stripped Chassis - Ford 7.3L 99N 8 CYL

8362 Tamarack Village Saint Paul, MN 55125

Unit #: 436038

Lic #: YCA7352

Cellular 949-338-2774				VIN #: 1F65F5KN1 M0A03024	
Part Description	Qty	Sale	Ext	Labor Description	Ext
Spark Plug	8.000	12.00	96.00	Work Requested: CEL is on	n/c
Plug Wire	8.000	28.00	224.00	Diagnostics	50.00
Cap fuel	1.000	23.15	23.15	Engine/transmission/ABS/vehicle Diagnostics	
Job Supplies			14.880	Labor	220.00
				Scan for engine codes, random misfires, misfires at start up, misfires on cylinders 1,2 & 3, EVAP leak codes present. Replace spark plugs and wires, clear codes.	
				Labor Test EVAP system, found seal on fuel cap failed, replace cap. No EVAP codes in system now. [Recommendations] PM due by 7/8/2023 or 43,000 miles to extend the life of your vehicle.	27.50
				FAI due by 4/30/2024	

Org. Estimate 681.35 Revisions 0.00 Current Estimate 681.35

297.50 Labor: Parts: 358.03

SubTotal: Tax:

655.53 25.82 681.35

Bal Due:

Total:

\$681.35

[Payments -]

Vehicle Received: 5/22/2023 Customer Number: 78

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: www.jobsiterepair.com