

**Job Site Repair LLC**  
 12015 Brockton Ln N  
 Maple Grove, MN. 55369  
 Phone: 763-428-8891 Fax: 866-454-6909

**INVOICE**

**231878**

**INVOICE**

Ref # : 436964

Printed Date: 05/18/2023

Work Completed: 05/16/2023

**Jet Delivers, Inc. - Jillian Helgerson**  
 2870 Goldenrod Way  
 Long Lake, MN 55356  
 Cellular 651-442-2857

2020 Ford - F59 Stripped Chassis - Ford 7.3L 99N 8 CYL  
 Lic # : YBZ2952 Odometer In : 80787  
 Unit # : 436964  
 VIN # : 1F66F5KN4 L0A03232

Part Description	Qty	Sale	Ext	Labor Description	Ext
Job Supplies			3.940	Work Requested: Mud flap stuck, roof drip edge damaged	n/c
				Labor	78.75
				Straighten both bent up mud flap anti-sail brackets. Remove damaged portion of roof drip edge.	
				<b>[ Recommendations ]</b>	
				PM due by 9/5/2023 or 83,806 miles to extend the life of your vehicle.	
				FAI due by 6/30/2023	

Org. Estimate 82.69      Revisions 0.00      Current Estimate 82.69

<b>Labor:</b>	<b>78.75</b>
<b>Parts:</b>	<b>3.94</b>
<b>SubTotal:</b>	<b>82.69</b>
<b>Tax:</b>	<b>0.00</b>
<b>Total:</b>	<b>82.69</b>
<b>Bal Due:</b>	<b>\$82.69</b>

[ Payments - ]

Vehicle Received: 5/16/2023

Customer Number : 64

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: [www.jobsiterepair.com](http://www.jobsiterepair.com)

Email Address: [jeff@jobsiterepair.com](mailto:jeff@jobsiterepair.com)