Job Site Repair LLC

12015 Brockton Ln N Maple Grove, MN. 55369

Phone: 763-428-8891 Fax: 866-454-6909

INVOICE

231932

INVOICE Work Completed: 05/18/2023 Ref #: 465717 Printed Date: 05/21/2023

Skol Corporation - Parth Lparel

Lic #: PML4770

2021 Ford - F59/F53 Stripped Chassis - Ford 7.3L 99N 8 CYL Odometer In: 23858

7161 Pleasant View Drive Saint Paul, MN 55112

Unit #: 465717

			VIN #: 1F66F5KN8 M0A04207	
Qty	Sale	Ext	Labor Description	Ext
8.000	4.45	35.60	Work Requested: Federal Annual Inspection	n/c
1.000	8.46	8.46	PM Service	80.00
1.000	20.32	20.32	Change oil, oil filter, lube vehicle	
2.000	4.09	8.18	Labor	220.00
1.000	3.39	3.39	During PM inspection found front brake pads under 5 MM thick,	
2.000	72.75	145.50		
2.000	7.14	14.28		220.00
1.000	24.71	24.71		
1.000	65.62	65.62		27.50
8.000	0.74	5.92	Replace broken doghouse latches	
1.000	10.31	10.31	Labor	82.50
1.000	8.48	8.48 48.130	Electric brake motor not working, trace to faulty relay, replace relay. Factory brake light switch broken, replace switch. Brake system works as designed now. Labor Inspect lights, replace broken lower right rear marker light. All lights work properly after repairs. Labor Front main seal leaking, remove front cover, replace seal and reassemble. Clean out engine bay, no leaks visible after repairs. Inspection Vehicle Inspection & PASSED after above repairs [Recommendations] PM due by 9/18/2023 or 27,858 miles to extend the life of your vehicle. FAI due by 5/31/2024	27.50 220.00 85.00
	8.000 1.000 1.000 2.000 1.000 2.000 2.000 1.000 8.000 1.000	8.000 4.45 1.000 8.46 1.000 20.32 2.000 4.09 1.000 3.39 2.000 72.75 2.000 7.14 1.000 24.71 1.000 65.62 8.000 0.74 1.000 10.31	8.000 4.45 35.60 1.000 8.46 8.46 1.000 20.32 20.32 2.000 4.09 8.18 1.000 3.39 3.39 2.000 72.75 145.50 2.000 7.14 14.28 1.000 24.71 24.71 1.000 65.62 65.62 8.000 0.74 5.92 1.000 10.31 10.31 1.000 8.48 8.48	QtySaleExtLabor Description8.0004.4535.60Work Requested: Federal Annual Inspection1.0008.468.46PM Service2.0004.098.18Labor1.0003.393.39During PM inspection found front brake pads under 5 MM thick, replace pads.2.0007.1414.281.00024.7124.711.00065.6265.628.0000.745.921.00010.3110.311.0008.4848.1308.48Electric brake motor not working, trace to faulty relay, replace relay.Factory brake light switch broken, replace switch. Brake system works as designed now.LaborInspect lights, replace broken lower right rear marker light. All lights work properly after repairs.LaborFront main seal leaking, remove front cover, replace seal and reassemble. Clean out engine bay, no leaks visible after repairs.InspectionVehicle Inspection & PASSED after above repairs[Recommendations]PM due by 9/18/2023 or 27,858 miles to extend the life of your vehicle.

1,387.27 Revisions 0.00 Current Estimate 1,387.27 Org. Estimate

962.50 Labor: Parts: 398.90

SubTotal: Tax:

1,361.40 25.87

Total:

1,387.27 \$1,387.27

Bal Due:

[Payments -]

Vehicle Received: 5/18/2023 Customer Number: 74

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: www.jobsiterepair.com