## Job Site Repair LLC

12015 Brockton Ln N Maple Grove, MN. 55369

Phone: 763-428-8891 Fax: 866-454-6909

INVOICE

231752

Odometer In: 54329

**INVOICE** Ref #: 470191 Printed Date: 05/11/2023 **Work Completed: 05/09/2023** 

RJH Delivery, Inc. - Ryan Husband

2021 Ford - F59/F53 Stripped Chassis - Ford 7.3L 99N 8 CYL

8362 Tamarack Village Woodbury, MN 55125

Unit #: 470191

Lic #: YCA7383

Cellular 949-338-2774

VIN # · 1F64F5KN7 M0A07283

| Celiulai 949-330-2114 |       |       |       | VIN # : 1F04F3KN/ WUAU/283   |       |
|-----------------------|-------|-------|-------|--|-------|
| Part Description      | Qty   | Sale  | Ext   | Labor Description  | Ext   |
| Light Amber LED       | 1.000 | 10.93 |       | Work Requested: Inspect lights                                       | n/c   |
| Job Supplies          |       |       | 1.380 | Labor  | 27.50 |
|                       |       |       |       | Inspect lights, Replace burnt out front upper left marker light. All |       |
|                       |       |       |       | lights work properly after repairs.                                  |       |
|                       |       |       |       | [ Recommendations ]  |       |
|                       |       |       |       | PM due by 7/22/2023 or 53,458 miles to extend the life of your       |       |
|                       |       |       |       | vehicle.   |       |
|                       |       |       |       | FAI due by 5/31/2024   |       |

Org. Estimate 40.62 Revisions 0.00 Current Estimate 40.62

Parts: 12.31

SubTotal: Tax: Total:

Labor:

0.81 40.62

39.81

27.50

Bal Due:

: 40.62 oue: \$40.62

[ Payments - ]

Vehicle Received: 5/9/2023 Customer Number : 47

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: www.jobsiterepair.com