Job Site Repair LLC
12015 Brockton Ln N
Maple Grove, MN. 55369
Phone: 763-428-8891 Fax: 866-454-6909

INVOICE
230715

INVOICE

Ref # : 86733 Printed Date: 02/25/2023 **Work Completed: 02/21/2023**

JND Deliveries - Jeff Schissler
1800 Como Ave. Suite 200F
Saint Paul, MN 55108
Cellular 612-385-0644

2012 Freightliner - Van Chassis - MT-55 - Cummins ISB6.7 CM2250 6 (
Lic # : YBW1328 Odometer In : 293179
Unit # : 86733
VIN # : 4UZAARDU6 **CCBK9204**

Part Description	Qty	Sale	Ext
Catch plate rear door M/Olson	1.000	91.62	91.62
Rollers door 1 inch	4.000	2.16	8.64
Job Supplies			11.000

Labor Description	Ext
Work Requested: Rear door will not stay closed	n/c
Labor	220.00

Inspect rear door, found catch plate broken off. Replace catch plate, drill new holes and fasten in place. Replace 4 missing door rollers. One door panel separating, bolt hinges back together. Lube and adjust door. Recommend entire door replacement.

[Recommendations]
FAI due by 6/30/2023
PM due by 4/25/2023 or 290,574 miles to extend the life of your vehicle.
Maintenance interval due 1/24/2023 to your vehicle.

Org. Estimate 338.65 Revisions 0.00 Current Estimate 338.65

Labor:	**220.00**
Parts:	**111.26**
SubTotal:	**331.26**
Tax:	**7.39**
Total:	**338.65**
Bal Due:	**$338.65**

[Payments -]

Vehicle Received: 2/21/2023

Customer Number : 65

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: www.jobsiterepair.com Email Address: ***jeff@jobsiterepair.com***

Copyright (c) 2023 Mitchell Repair Information Company, LLC invhrs 5.12.21kr