Job Site Repair LLC
12015 Brockton Ln N
Maple Grove, MN. 55369
Phone: 763-428-8891 Fax: 866-454-6909

INVOICE
231646

INVOICE

Ref # : 406990 Printed Date: 05/05/2023 **Work Completed: 05/01/2023**

JacobTransport Inc. - John Groppoli
1287 Arrowwood Trail
Hudson, WI 54016
Cellular 651-261-0128

2018 Freightliner - Van Chassis - MT-55 - Power Solutions International
Lic # : YBU6544 Odometer In : 93353
Unit # : 406990
VIN # : 4UZAC3EA3 **JCJJ9865**

Part Description	Qty	Sale	Ext
Headlight	1.000	17.24	17.24
Job Supplies			2.750

Labor Description	Ext
Work Requested: Inspect lights	n/c
Labor	55.00
Inspect lights, replace cracked drivers side headlight. Wiring in passenger side hood connector loose, secure wiring and connection. All lights work properly after repairs.	

Org. Estimate 76.29 Revisions 0.00 Current Estimate 76.29

Labor:	**55.00**
Parts:	**19.99**
SubTotal:	**74.99**
Tax:	**1.30**
Total:	**76.29**
Bal Due:	**$76.29**

[Payments -]

Vehicle Received: 5/1/2023

Customer Number : 113

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: www.jobsiterepair.com

Email Address:***jeff@jobsiterepair.com***

Copyright (c) 2023 Mitchell Repair Information Company, LLC invhrs 5.12.21kr