Job Site Repair LLC
12015 Brockton Ln N
Maple Grove, MN. 55369
Phone: 763-428-8891 Fax: 866-454-6909

INVOICE
224406

INVOICE

Ref # : 413067 Printed Date: 10/25/2022 **Work Completed: 10/24/2022**

Groundforce, Inc. - Gayle Gammel
472 Springhill Road
Vadnais Heights, MN 55127
Cellular 651-402-5977

2019 Freightliner - Van Chassis - MT-45 -
Lic # : YBW6908
Unit # : 413067
VIN # : 4UZAC3EA8 **KCKS7318**
Odometer In : 68822

Part Description	Qty	Sale	Ext
Seat belt 3 point	1.000	128.63	128.63
Job Supplies			4.130

Labor Description	Ext
Work Requested: Replace drivers side seat belt. Drivers states power steering not operating smoothly.	n/c
Labor Replace damaged drivers side seat belt, tighten and adjust.	55.00
Labor Inspect power steering, fluid full and operating normally. Lube chassis.	27.50

[Recommendations]
FAI due by 9/30/2023

Org. Estimate 224.75 Revisions 0.00 Current Estimate 224.75

Labor:	**82.50**
Parts:	**132.76**
SubTotal:	**215.26**
Tax:	**9.49**
Total:	**224.75**
Bal Due:	**$224.75**

[Payments -]

Vehicle Received: 10/24/2022

Customer Number : 21

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: www.jobsiterepair.com

Email Address:***jeff@jobsiterepair.com***

Copyright (c) 2022 Mitchell Repair Information Company, LLC invhrs 5.12.21kr