Job Site Repair LLC
12015 Brockton Ln N
Maple Grove, MN. 55369
Phone: 763-428-8891 Fax: 866-454-6909

INVOICE
230132

INVOICE

Ref # : 414132 Printed Date: 01/12/2023 **Work Completed: 01/10/2023**

VP Transport - Parth Lparel
7161 Pleasant View Drive
Saint Paul, MN 55112
Cellular 651-206-8345

2019 Ford - F59/F53 Stripped Chassis - Ford 6.8L 99Y F59 10 CYL
Lic # : YBX4437 Odometer In : 91523
Unit # : 414132
VIN # : 1F65F5KYX **K0A08536**

Part Description	Qty	Sale	Ext
Light Amber LED	1.000	10.93	10.93
Job Supplies			1.380

Labor Description	Ext
Work Requested: Inspect lights	n/c
Labor	27.50

Inspect lights, replace melted drivers side hood marker light. All lights work properly after repairs.

[Recommendations]
PM due by 2/27/2023 or 90,579 miles to extend the life of your vehicle.
FAI due by 3/31/2023
King pins starting to have slight play, recommend replacing at next PM

Org. Estimate 40.63 Revisions 0.00 Current Estimate 40.63

Labor:	**27.50**
Parts:	**12.31**
SubTotal:	**39.81**
Tax:	**0.82**
Total:	**40.63**
Bal Due:	**$40.63**

[Payments -]

Vehicle Received: 1/10/2023

Customer Number : 89

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: www.jobsiterepair.com Email Address: ***jeff@jobsiterepair.com***

Copyright (c) 2023 Mitchell Repair Information Company, LLC invhrs 5.12.21kr