Job Site Repair LLC
12015 Brockton Ln N
Maple Grove, MN. 55369
Phone: 763-428-8891 Fax: 866-454-6909

INVOICE
224301

INVOICE

Ref # : 436965 Printed Date: 10/18/2022 **Work Completed: 10/17/2022**

Jet Delivers, Inc. - Jillian Helgerson
2870 Goldenrod Way
Long Lake, MN 55356
Cellular 651-442-2857

2020 Ford - F59 Stripped Chassis - Ford 7.3L 99N 8 CYL
Lic # : YBZ2989 Odometer In : 77348
Unit # : 436965
VIN # : 1F66F5KN4 **L0A04364**

Part Description	Qty	Sale	Ext
Blower Housing Evans style	1.000	48.13	48.13
Cap fuel tethered	1.000	19.98	19.98
Job Supplies			6.560

Labor Description	Ext
Work Requested: No heat	n/c
Labor	105.00
Inspect for cause of no heat found blower motor housing broken and not connected to HVAC system. Replace blower housing and secure. System works fine after repairs.	
Labor	26.25
CEL is on, could not connect to vehicle smart plug faulty. Order new plug and will install when parts arrives. Check fuel cap light on, inspect cap and seal is torn, replace cap.	

[Recommendations]
PM due by 1/14/2023 or 77,988 miles to extend the life of your vehicle.
FAI due by 6/30/2023

Org. Estimate 211.05 Revisions 0.00 Current Estimate 211.05

Labor:	**131.25**
Parts:	**74.67**
SubTotal:	**205.92**
Tax:	**5.13**
Total:	**211.05**
Bal Due:	**$211.05**

[Payments -]

Vehicle Received: 10/17/2022

Customer Number : 64

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: www.jobsiterepair.com Email Address: ***jeff@jobsiterepair.com***

Copyright (c) 2022 Mitchell Repair Information Company, LLC invhrs 5.12.21kr