Job Site Repair LLC
12015 Brockton Ln N
Maple Grove, MN. 55369
Phone: 763-428-8891 Fax: 866-454-6909

INVOICE
231718

INVOICE

Ref # : 472246 Printed Date: 05/09/2023 **Work Completed: 05/05/2023**

RJH Delivery, Inc. - Ryan Husband
8362 Tamarack Village
Woodbury, MN 55125
Cellular 949-338-2774

2021 Ford - F59/F53 Stripped Chassis - Ford 7.3L 99N 8 CYL
Lic # : YCA7394 Odometer In : 18799
Unit # : 472246
VIN # : 1F66F5KN7 **M0A02853**

Part Description	Qty	Sale	Ext
245/70/19.5 DC RT600	1.000	251.55	251.55
Tire Disposal	1.000	15.00	15.00
Job Supplies			6.250

Labor Description	Ext
Work Requested: Federal Annual Inspection	n/c
Labor tire	40.00
Replace drivers side steer tire and balance, air to 100 PSI. Existing tire was at 2/32", no customer owned tire of this size available.	
Inspection	85.00
Vehicle Inspection & PASSED after above repairs	

[Recommendations]
PM due by 7/21/2023 or 21,453 miles to extend the life of your vehicle.
FAI due by 5/31/2024

Org. Estimate 416.35 Revisions 0.00 Current Estimate 416.35

Labor:	**125.00**
Parts:	**257.80**
Tire Fees:	**15.000**
SubTotal:	**397.80**
Tax:	**18.55**
Total:	**416.35**
Bal Due:	**$416.35**

[Payments -]

Vehicle Received: 5/5/2023

Customer Number : 47

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: www.jobsiterepair.com

Email Address:***jeff@jobsiterepair.com***

Copyright (c) 2023 Mitchell Repair Information Company, LLC invhrs 5.12.21kr