Job Site Repair LLC
12015 Brockton Ln N
Maple Grove, MN. 55369
Phone: 763-428-8891 Fax: 866-454-6909

INVOICE
225203

INVOICE

Ref # : 475500 Printed Date: 12/15/2022 **Work Completed: 12/13/2022**

Dilly Logistics, Inc. - Vandan Vekaria
7008 92nd Ave. N.
Brooklyn Park, MN 55445
Cellular 651-410-4911

2021 Ford - F59/F53 Stripped Chassis - Ford 7.3L 99N 8 CYL
Lic # : PLF9074 Odometer In : 19610
Unit # : 475500
VIN # : 1F65F5KN6 **M0A14066**

Part Description	Qty	Sale	Ext
Oil 10W30 Citgard 600	8.500	4.22	35.87
Filter oil	1.000	8.36	8.36
W/ Washer Fluid	1.000	3.50	3.50
W/wiper blade	2.000	7.91	15.82
Brake Disc Pads	1.000	72.75	72.75
Job Supplies			16.380

Labor Description	Ext
Work Requested: PM	n/c
PM Service Change oil, oil filter, lube vehicle	80.00
Labor Replace worn wiper blades	27.50
Labor During PM inspection found rear brake pads under 5 MM thick, replace pads.	220.00

[Recommendations]
PM due by 4/13/2023 or 23,610 miles to extend the life of your vehicle.
FAI due by 11/30/2023

Org. Estimate 490.44 Revisions 0.00 Current Estimate 490.44

Labor:	**327.50**
Parts:	**152.68**
SubTotal:	**480.18**
Tax:	**10.26**
Total:	**490.44**
Bal Due:	**$490.44**

[Payments -]

Vehicle Received: 12/13/2022

Customer Number : 92

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: www.jobsiterepair.com

Email Address:***jeff@jobsiterepair.com***

Copyright (c) 2022 Mitchell Repair Information Company, LLC invhrs 5.12.21kr