Job Site Repair LLC
12015 Brockton Ln N
Maple Grove, MN. 55369
Phone: 763-428-8891 Fax: 866-454-6909

INVOICE
231852

INVOICE

Ref # : 475505 Printed Date: 05/16/2023 **Work Completed: 05/15/2023**

Dilly Logistics, Inc. - Vandan Vekaria
7008 92nd Ave. N.
Brooklyn Park, MN 55445
Cellular 651-410-4911

2021 Ford - F59/F53 Stripped Chassis - Ford 7.3L 99N 8 CYL
Lic # : PLF9071 Odometer In : 28171
Unit # : 475505
VIN # : 1F65F5KN6 **M0A16769**

Part Description	Qty	Sale	Ext
Fuse	1.000	1.00	1.00
Job Supplies			2.750

Labor Description	Ext
Work Requested: Inspect lights	n/c
Labor	55.00

Inspect lights, cargo lights out and fuse blown again. Trace issue to locate reason for fuse blowing, found wire rubbed through in overhead compartment over drivers seat, repair wiring. All lights work properly after repairs.

[Recommendations]
PM due by 7/22/2023 or 27,835 miles to extend the life of your vehicle.
FAI due by 12/31/2023

Org. Estimate 58.83 Revisions 0.00 Current Estimate 58.83

Labor:	**55.00**
Parts:	**3.75**
SubTotal:	**58.75**
Tax:	**0.08**
Total:	**58.83**
Bal Due:	**$58.83**

[Payments -]

Vehicle Received: 5/15/2023

Customer Number : 92

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: www.jobsiterepair.com Email Address: ***jeff@jobsiterepair.com***

Copyright (c) 2023 Mitchell Repair Information Company, LLC invhrs 5.12.21kr