Job Site Repair LLC
12015 Brockton Ln N
Maple Grove, MN. 55369
Phone: 763-428-8891 Fax: 866-454-6909

INVOICE
224475

INVOICE

Ref # : 87165 Printed Date: 10/28/2022 **Work Completed: 10/27/2022**

Midwest Deliveries, Inc. - Ryan Brunette
489 Omaha Road
Hudson, WI 54016
Cellular 651-775-7381

2013 Freightliner - Van Chassis - MT-55 - Cummins ISB6.7 CM2250 6 (
Lic # : PLB4728 Odometer In : 427853
Unit # : 87165
VIN # : 4UZAARDU2 **DCFE4694**

Part Description	Qty	Sale	Ext
Rotor	1.000	162.80	162.80
Seal	1.000	42.43	42.43
Bearing race wheel	1.000	28.03	28.03
Bearing wheel	1.000	30.37	30.37
Brake Caliper	1.000	136.02	136.02
Brake line	1.000	11.86	11.86
Oil 80/90 Quart	1.000	5.83	5.83
Brake Pads	1.000	72.75	72.75
245/70/19.5 Steer SC020	1.000	301.17	301.17
Tire Disposal	1.000	8.00	8.00
Job Supplies			25.130

Labor Description	Ext
Work Requested: Drivers side front caliper leaking.	n/c
Labor	472.50
Inspect front brakes, found drivers side went metal on metal blowing caliper and damaging rotor. Remove hub, oil was very thick, remove bearings, worn and pitted. Clean up hub and replace bearings. Reassemble with new rotor, caliper, brake line and wheel seal. Fill hub oil. Bleed brake system.Replace front brake pads.	
Labor tire	30.00
Replace drivers side steer tire and balance, air to 100 PSI. Existing tire was at 4/32"	

[Recommendations]
PM due by 6/27/2022 or 419,472 miles to extend the life of your vehicle.
FAI due by 1/31/2023
Maintenance interval due 3/27/2022 to your vehicle.

Org. Estimate 1,385.25 Revisions 0.00 Current Estimate 1,385.25

Labor:	**502.50**
Parts:	**816.39**
Tire Fees:	**8.000**
SubTotal:	**1,326.89**
Tax:	**58.36**
Total:	**1,385.25**
Bal Due:	**$1,385.25**

[Payments -]

Vehicle Received: 10/27/2022

Customer Number : 61

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: www.jobsiterepair.com Email Address: ***jeff@jobsiterepair.com***

Copyright (c) 2022 Mitchell Repair Information Company, LLC invhrs 5.12.21kr