

Job Site Repair LLC
 12015 Brockton Ln N
 Maple Grove, MN. 55369
 Phone: 763-428-8891 Fax: 866-454-6909

INVOICE

231861

INVOICE

Ref # : 203342

Printed Date: 05/17/2023

Work Completed: 05/16/2023

JJH Transport Corp. - Josh Hanson
 14355 Irish Ave. N.
 Hugo, MN 55038
 Cellular 651-558-1239

2015 International - DuraStar Series - 4300 - International MaxxForce C
 Lic # : YBX7952 Odometer In : 175318
 Unit # : 203342
 VIN # : 1HTMMAAL0 FH517350

Part Description	Qty	Sale	Ext	Labor Description	Ext
Seal H/P oil rail	1.000	164.98	164.98	Work Requested: Tow in, vehicle keeps shutting down	n/c
Kit injector seal	2.000	30.20	60.40	Towing	279.04
Injector	2.000	767.34	1,534.68	Tow from Woodbury to Mahtomedi shop	
Job Supplies			46.950	Labor	660.00
				Inspect for cause of engine shutting down. Remove valve cover and injector oil rail. Found cup for injector # 5 cracked, cylinder head needs replacement. Vehicle has engine known for early failure, can not recommend spending money on head replacement. Clean up injector cups and replace failed injectors #1 & 5, reassemble. Test drive, get truck to 65 MPH, engine running good now, no CEL returning, but more than likely not or long, maybe 6 months. Injecors can not be warranty do to head damage.	
				[Recommendations]	
				FAI due by 6/30/2023	
				PM due by 3/10/2023 or 178,780 miles to extend the life of your vehicle.	
				Maintenance interval due 1/19/2023 to your vehicle.	

Org. Estimate 2,875.85 Revisions 0.00 Current Estimate 2,875.85

Labor:	660.00
Parts:	1,807.01
Sublet:	279.04
SubTotal:	2,746.05
Tax:	129.80
Total:	2,875.85
Bal Due:	\$2,875.85

[Payments -]

Vehicle Received: 5/16/2023

Customer Number : 29

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: www.jobsiterepair.com

Email Address: jeff@jobsiterepair.com