## Job Site Repair LLC

12015 Brockton Ln N Maple Grove, MN. 55369

Phone: 763-428-8891 Fax: 866-454-6909

INVOICE

224380

INVOICE Ref #: 204651 Printed Date: 10/21/2022

2016 Freightliner - M2 Series - M2-106 - Cummins ISB6.7 CM2350 6 C

Lic # : YBZ6630

Odometer In: 248099

Work Completed: 10/20/2022

Unit #: 204651

VIN #: 3ALACWDT8 GDHA4616

	VIIVII : O/LE/COVE TO CETATION				
Part Description	Qty	Sale	Ext	Labor Description	Ext
Fuse holder	1.000	6.71	6.71	Work Requested: 12 volt charging ports not working	n/c
Fuse	1.000	1.00	1.00	Labor	165.00
Charger USB dual Job Supplies	1.000	26.44	26.44 8.250	Inspect 12 volt charging ports, fuses good, trace wiring trouble in BCM. Run new wiring to 12 volt power outlet direct from battery. Install new fuse holder and another charging port. All ports and VEDR camera work after repairs.	

[ Recommendations ]

PM due by 11/5/2022 or 247,648 miles to extend the life of your vehicle

FAI due by 1/31/2023

Maintenance interval due 8/5/2022 to your vehicle.

Org. Estimate 209.97 Revisions 0.00 Current Estimate 209.97

Labor: 165.00 Parts: 42.40

SubTotal: Tax: 207.40 2.57 209.97

\$209.97

Total: Bal Due:

\_\_\_\_\_

[ Payments - ]

Vehicle Received: 10/20/2022 Customer Number : 81

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: www.jobsiterepair.com

North Star Courier - Mitch Boeder

7347 Sping Lake Road

Saint Paul, MN 55112

Cellular 507-351-5599