

**Job Site Repair LLC**

12015 Brockton Ln N

Maple Grove, MN. 55369

Phone: 763-428-8891 Fax: 866-454-6909

**INVOICE****231661****INVOICE**

Ref #: 307078

Printed Date: 05/05/2023

**Work Completed: 05/02/2023****Midwest Deliveries, Inc. - Ryan Brunette**489 Omaha Road  
Hudson, WI 54016  
Cellular 651-775-7381

2013 Ford - F59 Stripped Chassis - Ford 6.8L 99Y F59 10 CYL

Lic #: FB38178

Odometer In : 179432

Unit #: 307078

VIN #: 1F66F5KY0 D0A06849

Part Description	Qty	Sale	Ext	Labor Description	Ext
Lever	1.000	78.34	78.34	Work Requested: No start	n/c
Bushing	2.000	4.43	8.86	Labor	157.50
Lever shifter damper	1.000	20.92	20.92	Vehicle towed in for no start, found shifter assembly worn out, we wiggled shifter and vehicle starts fine. Remove steering column covers, rebuild shifter assembly and reassemble. Vehicle shifts fine and starts reliably after repairs.	
Clamp tube shifter	2.000	22.49	44.98		
Tube shifter	1.000	71.89	71.89		
Plunger shifter	1.000	41.21	41.21		
Tube shifter spring	1.000	13.67	13.67		
Job Supplies			7.880		

**[ Recommendations ]**

FAI due by 2/28/2024

PM due by 8/7/2023 or 181,805 miles to extend the life of your vehicle.

Org. Estimate 465.89 Revisions 0.00 Current Estimate 465.89

<b>Labor:</b>	<b>157.50</b>
<b>Parts:</b>	<b>287.75</b>
<b>SubTotal:</b>	<b>445.25</b>
<b>Tax:</b>	<b>20.64</b>
<b>Total:</b>	<b>465.89</b>
<b>Bal Due:</b>	<b>\$465.89</b>

[ Payments - ]

Vehicle Received: 5/2/2023

Customer Number : 61

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: [www.jobsiterepair.com](http://www.jobsiterepair.com)Email Address: [jeff@jobsiterepair.com](mailto:jeff@jobsiterepair.com)