

**Job Site Repair LLC**  
12015 Brockton Ln N  
Maple Grove, MN. 55369  
Phone: 763-428-8891 Fax: 866-454-6909

**INVOICE**

**225239**

**INVOICE**

Ref # : 311329

Printed Date: 12/17/2022

Work Completed: 12/15/2022

**Midwest Deliveries, Inc. - Ryan Brunette**

489 Omaha Road  
Hudson, WI 54016  
Cellular 651-775-7381

2013 Ford - F59 Stripped Chassis - Ford 6.8L 99Y F59 10 CYL

Lic # : FB49137

Odometer In : 154029

Unit # : 311329

VIN # : 1F66F5KY8 D0A12768

Part Description	Qty	Sale	Ext	Labor Description	Ext
Differential	1.000	2,738.45	2,738.45	Work Requested: Towed in, will not move, loud noise	n/c
Oil 75/90	8.000	11.44	91.52	from rear end.	
Job Supplies			31.500	Labor	630.00
				Inspect vehicle and found rear differential failed, advise owner and order parts. Remove both axles, drive line, and pinion yoke. Install yoke on new differential and install in vehicle. Clean axle tubes and install axles, fill fluid. No leaks visible and vehicle drives fine after repairs.	
				<b>[ Recommendations ]</b>	
				PM due by 9/19/2022 or 153,000 miles to extend the life of your vehicle.	
				FAI due by 10/31/2023	

Org. Estimate 3,700.18 Revisions 0.00 Current Estimate 3,700.18

<b>Labor:</b>	<b>630.00</b>
<b>Parts:</b>	<b>2,861.47</b>
<b>SubTotal:</b>	<b>3,491.47</b>
<b>Tax:</b>	<b>208.71</b>
<b>Total:</b>	<b>3,700.18</b>
<b>Bal Due:</b>	<b>\$3,700.18</b>

[ Payments - ]

Vehicle Received: 12/15/2022

Customer Number : 61

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: [www.jobsiterepair.com](http://www.jobsiterepair.com)

Email Address: [jeff@jobsiterepair.com](mailto:jeff@jobsiterepair.com)