

**Job Site Repair LLC**  
 12015 Brockton Ln N  
 Maple Grove, MN. 55369  
 Phone: 763-428-8891 Fax: 866-454-6909

**INVOICE**

**231823**

**INVOICE**

Ref # : 321154

Printed Date: 05/15/2023

Work Completed: 05/12/2023

**North Star Courier - Mitch Boeder**  
 7347 Sping Lake Road  
 Saint Paul, MN 55112  
 Cellular 507-351-5599

2016 Ford - F59 Stripped Chassis - Ford 6.8L 99Y F59 10 CYL  
 Lic # : YBN0548 Odometer In : 165144  
 Unit # : 321154  
 VIN # : 1F66F5KY6 G0A00994

Part Description	Qty	Sale	Ext	Labor Description	Ext
Pull Strap	1.000	19.56	19.56	Work Requested: Rear door pull strap broken	n/c
Yoke	1.000	200.69	200.69	Labor	27.50
Job Supplies			5.500	Dill out rivets for rear door pull down strap, replace strap and rivet in place.	
				Labor	82.50
				Noticed steering hard on drive to shop, found steering yoke failing, replace yoke. Steering normal after repairs. Engine has noticeable ticking/ lifter noise.	
				<b>[ Recommendations ]</b>	
				PM due by 6/10/2023 or 165,373 miles to extend the life of your vehicle.	
				FAI due by 9/30/2023	

Org. Estimate 352.32      Revisions 0.00      Current Estimate 352.32

<b>Labor:</b>	<b>110.00</b>
<b>Parts:</b>	<b>225.75</b>
<b>SubTotal:</b>	<b>335.75</b>
<b>Tax:</b>	<b>16.57</b>
<b>Total:</b>	<b>352.32</b>
<b>Bal Due:</b>	<b>\$352.32</b>

[ Payments - ]

Vehicle Received: 5/12/2023

Customer Number : 81

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: [www.jobsiterepair.com](http://www.jobsiterepair.com)

Email Address: [jeff@jobsiterepair.com](mailto:jeff@jobsiterepair.com)