

Job Site Repair LLC

12015 Brockton Ln N

Maple Grove, MN. 55369

Phone: 763-428-8891 Fax: 866-454-6909

INVOICE**231916****INVOICE**

Ref #: 324979

Printed Date: 05/19/2023

Work Completed: 05/18/2023**AZAL, Inc. - Ali Aldera**

7317 W Franklin Ave.

St. Louis Park, MN 55426

Office 612-803-1511 Ali Aldera

Cellular 651-666-3354 Ryan Fritz

2017 Freightliner - Van Chassis - MT-55 - Cummins ISB6.7 CM2350 6 (

Lic #: YBR3605

Odometer In : 172501

Unit #: 324979

VIN #: 4UZAARDU7 HCHW8487

Part Description	Qty	Sale	Ext	Labor Description	Ext
Rollers door 1 inch	20.000	2.16	43.20	Work Requested: CEL is on, repair floor in cargo area,	n/c
Rivets 1/4	4.000	0.72	2.88	rear door out of track.	
Job Supplies			19.000	Labor	137.50
				Inspect rear door, replace all door rollers, existing rollers either broken, missing or seized up. Lube and adjust door. Door works fine after repairs.	
				Labor	27.50
				Secure loose access panel in floor of cargo area with new rivets.	
				Diagnostics	50.00
				Engine/transmission/ABS/vehicle Diagnostics	
				Labor	165.00
				Scan for engine codes, poor DEF quality and low DEF fluid present. DEF had just been filled at 98%, run forced regeneration, passed. Clear codes and test drive with no warning lights returning after repairs.	
				[Recommendations]	
				PM due by 8/3/2023 or 175,000 miles to extend the life of your vehicle.	
				FAI due by 5/31/2024	

Org. Estimate 448.55 Revisions 0.00 Current Estimate 448.55

Labor:	380.00
Parts:	65.08
SubTotal:	445.08
Tax:	3.47
Total:	448.55
Bal Due:	\$448.55

[Payments -]

Vehicle Received: 5/18/2023

Customer Number : 4

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: www.jobsiterepair.comEmail Address: jeff@jobsiterepair.com