

**Job Site Repair LLC**  
12015 Brockton Ln N  
Maple Grove, MN. 55369  
Phone: 763-428-8891 Fax: 866-454-6909

**INVOICE**

**231943**

**INVOICE**

Ref # : 327212

Printed Date: 05/22/2023

Work Completed: 05/19/2023

**Midwest Deliveries, Inc. - Ryan Brunette**

489 Omaha Road  
Hudson, WI 54016  
Cellular 651-775-7381

2016 Ford - F59 Stripped Chassis - Ford 6.8L 99Y F59 10 CYL

Lic # : FB49143

Odometer In : 123739

Unit # : 327212

VIN # : 1F66F5KY2 G0A09661

Part Description	Qty	Sale	Ext	Labor Description	Ext
B post Door strike R/H	1.000	123.17	123.17	Work Requested: Catch plate snapped off drivers door.	n/c
Job Supplies			2.630	Labor	52.50
				Inspect drivers side door, found open striker broken, replace striker and rubber stop. Lube and adjust door, door latches open after repairs.	
				<b>[ Recommendations ]</b>	
				PM due by 8/28/2023 or 126,554 miles to extend the life of your vehicle.	
				FAI due by 4/30/2024	

Org. Estimate 187.38 Revisions 0.00 Current Estimate 187.38

<b>Labor:</b>	<b>52.50</b>
<b>Parts:</b>	<b>125.80</b>
<b>SubTotal:</b>	<b>178.30</b>
<b>Tax:</b>	<b>9.08</b>
<b>Total:</b>	<b>187.38</b>
<b>Bal Due:</b>	<b>\$187.38</b>

[ Payments - ]

Vehicle Received: 5/19/2023

Customer Number : 61

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: [www.jobsiterepair.com](http://www.jobsiterepair.com)

Email Address: [jeff@jobsiterepair.com](mailto:jeff@jobsiterepair.com)