

**Job Site Repair LLC**  
 12015 Brockton Ln N  
 Maple Grove, MN. 55369  
 Phone: 763-428-8891 Fax: 866-454-6909

**INVOICE**

**223316**

**INVOICE**

Ref # : 329817

Printed Date: 08/03/2022

Work Completed: 08/02/2022

**Jet Delivers, Inc. - Jillian Helgerson**

2870 Goldenrod Way  
 Long Lake, MN 55356  
 Cellular 651-442-2857

2017 Freightliner - Van Chassis - MT-45 -

Lic # : YBT3367

Odometer In : 136615

Unit # : 329817

VIN # : 4UZAC3EA5 HCJC4233

Part Description	Qty	Sale	Ext	Labor Description	Ext
Oil Dye	1.000	15.72	15.72	Work Requested:Check leaks	n/c
Degreaser	2.000	5.13	10.26	Labor	840.00
Crankshaft Sensor	1.000	63.05	63.05	Inspect for oil leaks, appears to be coming from several places from engine. Add oil dye to identify leaks per engine manufacturer recommendations. Degrease engine compartment. Leaks from oil drain plug, crankcase position sensor and front engine cover noted. Tighten oil plug, seal is fine. Remove starter no visible leaks from flywheel housing. Remove crankcase position sensor and replace, reinstall starter. Remove coolant reservoir, engine fan and shroud, water pump to access front cover. Remove cover, clean all surfaces and replace crankshaft seal. Reassemble with new gasket set. Clean engine compartment, change oil and filter. Road test and recheck for leaks, none visible after repairs.  <b>[ Recommendations ]</b> PM due by 12/2/2022 or 140,615 miles to extend the life of your vehicle. FAI due by 11/30/2022	
Hose clamp	2.000	1.00	2.00		
Harrmonic Bolt	1.000	7.06	7.06		
Front Crankshaft Seal	1.000	53.75	53.75		
Front Cover Gasket	1.000	57.73	57.73		
Oil Filter	1.000	5.88	5.88		
Oil 10W30 Citgard 600	6.000	4.00	24.00		
Job Supplies			42.000		

Org. Estimate 1,139.47    Revisions 0.00    Current Estimate 1,139.47

<b>Labor:</b>	<b>840.00</b>
<b>Parts:</b>	<b>281.45</b>
<b>SubTotal:</b>	<b>1,121.45</b>
<b>Tax:</b>	<b>18.02</b>
<b>Total:</b>	<b>1,139.47</b>
<b>Bal Due:</b>	<b>\$1,139.47</b>

[ Payments - ]

Vehicle Received: 8/2/2022

Customer Number : 64

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: [www.jobsiterepair.com](http://www.jobsiterepair.com)

Email Address: [jeff@jobsiterepair.com](mailto:jeff@jobsiterepair.com)