

**Job Site Repair LLC**  
 12015 Brockton Ln N  
 Maple Grove, MN. 55369  
 Phone: 763-428-8891 Fax: 866-454-6909

**INVOICE**

**225483**

**INVOICE**

Ref # : 405954

Printed Date: 12/31/2022

Work Completed: 12/30/2022

**JND Deliveries - Jeff Schissler**  
 1800 Como Ave. Suite 200F  
 Saint Paul, MN 55108  
 Cellular 612-385-0644

2007 Ford - E Series - E450SD - Ford 5.4L 99L E Series 8 CYL  
 Lic # : YBU6523 Odometer In : 248472  
 Unit # : 405954  
 VIN # : 1FCLE49LX 7DB33712

Part Description	Qty	Sale	Ext	Labor Description	Ext
Job Supplies			5.500	Work Requested: Losing power while driving	n/c
				Labor	110.00
				Inspect for cause of low poweer, fuel pressure sensor failing, order parts. Remove and clean dirty throttle body. Look for vehicle week of 12/ 25 could not find until 12/30 and fuel pressure sensor had been changed by someone else.	
				<b>[ Recommendations ]</b>	
				FAI due by 1/31/2023	

Org. Estimate 115.50      Revisions 0.00      Current Estimate 115.50

<b>Labor:</b>	<b>110.00</b>
<b>Parts:</b>	<b>5.50</b>
<b>SubTotal:</b>	<b>115.50</b>
<b>Tax:</b>	<b>0.00</b>
<b>Total:</b>	<b>115.50</b>
<b>Bal Due:</b>	<b>\$115.50</b>

[ Payments - ]

Vehicle Received: 12/30/2022

Customer Number : 65

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: [www.jobsiterepair.com](http://www.jobsiterepair.com)

Email Address: [jeff@jobsiterepair.com](mailto:jeff@jobsiterepair.com)