

**Job Site Repair LLC**  
 12015 Brockton Ln N  
 Maple Grove, MN. 55369  
 Phone: 763-428-8891 Fax: 866-454-6909

**INVOICE**

**231678**

**INVOICE**

Ref # : 411320

Printed Date: 05/05/2023

Work Completed: **05/03/2023**

**Tyton Companies - Matt Schreier**  
 13586 Foxberry Road  
 Savage, MN 55378  
 Home 763-300-2180 Steven  
 Cellular 952-270-9955 Matt

2018 Ford - F59/F53 Stripped Chassis - Ford 6.8L 99Y F59 10 CYL  
 Lic # : 167982 Odometer In : 110419  
 Unit # : 411320  
 VIN # : 1F66F5KY7 J0A03622

Part Description	Qty	Sale	Ext	Labor Description	Ext
Cap Fuel	1.000	24.18	24.18	Work Requested: CEL is on	n/c
Job Supplies			5.250	Diagnostics	50.00
				Engine/transmission/ABS/vehicle Diagnostics	
				Labor	55.00
				Scan for engine codes, 2 codes for large EVAP leaks present. Inspect EVAP system, found seal on fuel cap failed, replace cap and clear codes.	
				<b>[ Recommendations ]</b>	
				PM due by 7/27/2023 or 111,939 miles to extend the life of your vehicle.	
				FAI due by 7/31/2023	

Org. Estimate 136.25 Revisions 0.00 Current Estimate 136.25

<b>Labor:</b>	<b>105.00</b>
<b>Parts:</b>	<b>29.43</b>
<b>SubTotal:</b>	<b>134.43</b>
<b>Tax:</b>	<b>1.82</b>
<b>Total:</b>	<b>136.25</b>
<b>Bal Due:</b>	<b>\$136.25</b>

[ Payments - ]

Vehicle Received: 5/3/2023

Customer Number : 73

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: [www.jobsiterepair.com](http://www.jobsiterepair.com)

Email Address: [jeff@jobsiterepair.com](mailto:jeff@jobsiterepair.com)