## Job Site Repair LLC

12015 Brockton Ln N Maple Grove, MN. 55369

Phone: 763-428-8891 Fax: 866-454-6909

INVOICE

231867

INVOICE Ref #: 413067 Printed Date: 05/17/2023 Work Completed: 05/16/2023

Groundforce, Inc. - Gayle Gammel

472 Springhill Road

Vadnais Heights, MN 55127

Cellular 651-402-5977

2019 Freightliner - Van Chassis - MT-45 -

Lic # : YBW6908

Unit #: 413067

VIN #: 4UZAC3EA8 KCKS7318

Odometer In: 413067

Oddinotol III : 11000

Part Description	Qty	Sale	Ext	Labor Description	Ext
Oil hub cap	1.000	34.45	34.45	Work Requested: Replace drivers side front tire	n/c
Oil 80/90 Quart	0.500	6.94	3.47	Labor	82.50
245/70/19.5 DC RT600	1.000	251.55	251.55	Front drivers side wheel hub leaking, replace hub seal and fill fluid.	
Tire Disposal	1.000	15.00	15.00	Clean off rim.	
Job Supplies			6.130	Labor tire	40.00
• •				Replace drivers side steer tire and balance, air to 100 PSI	

[ Recommendations ]

FAI due by 9/30/2023

Org. Estimate 454.45 Revisions 0.00 Current Estimate 454.45

Labor: 122.50 Parts: 295.60

Tire Fees:

s: 15.000

SubTotal: Tax: 433.10 21.35

454.45

Total: Bal Due:

\$454.45

[ Payments - ]

Vehicle Received: 5/16/2023 Customer Number : 21

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: www.jobsiterepair.com

Email Address: jeff@jobsiterepair.com