

Job Site Repair LLC
12015 Brockton Ln N
Maple Grove, MN. 55369
Phone: 763-428-8891 Fax: 866-454-6909

INVOICE

231702

INVOICE

Ref # : 4114131

Printed Date: 05/08/2023

Work Completed: 05/04/2023

VP Transport - Parth Lparel

7161 Pleasant View Drive
Saint Paul, MN 55112
Cellular 651-206-8345

2019 Ford - F59/F53 Stripped Chassis - Ford 6.8L 99Y F59 10 CYL

Lic # : YBW1499

Odometer In : 104369

Unit # : 414131

VIN # : 1F65F5KY8 K0A08535

Part Description	Qty	Sale	Ext	Labor Description	Ext
Oil 10W30 Citgard 600	7.500	4.45	33.38	Work Requested: PM, CEL on	n/c
Filter oil	1.000	8.46	8.46	PM Service	80.00
Antifreeze Dex Cool	1.000	4.09	4.09	Change oil, oil filter, lube vehicle	
W/ Washer Fluid	1.000	3.39	3.39	Diagnostics	50.00
Cap fuel tethered	1.000	19.98	19.98	Engine/transmission/ABS/vehicle Diagnostics	
Job Supplies			12.000	Labor	110.00
				Scan for engine codes, codes for engine overspeed and EVAP leak present. Overspeed codes most likely from spinning tires on snow, codes inactive. Check EVAP system, found seal on fuel cap failed, replace cap and clear codes.	
				[Recommendations]	
				PM due by 9/4/2023 or 108,369 miles to extend the life of your vehicle.	
				FAI due by 3/31/2024	
				Transmission fluid flush, fluid dark in color	

Org. Estimate 326.51 Revisions 0.00 Current Estimate 326.51

Labor:	240.00
Parts:	81.30
SubTotal:	321.30
Tax:	5.21
Total:	326.51
Bal Due:	\$326.51

[Payments -]

Vehicle Received: 5/4/2023

Customer Number : 89

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: www.jobsiterepair.com

Email Address: jeff@jobsiterepair.com