Job Site Repair LLC

12015 Brockton Ln N
Manle Grove MN 55369

Maple Grove, MN. 55369

Phone: 763-428-8891 Fax: 866-454-6909

INVOICE

231973

INVOICE Work Completed: 05/22/2023 Ref #: 414132 Printed Date: 05/23/2023 2019 Ford - F59/F53 Stripped Chassis - Ford 6.8L 99Y F59 10 CYL **VP Transport - Parth Lparel** 7161 Pleasant View Drive Lic #: YBX4437 Odometer In: 100237 Saint Paul. MN 55112 Unit #: 414132 Cellular 651-206-8345 VIN #: 1F65F5KYX K0A08536 **Part Description** Sale Qty Ext **Labor Description** Ext Job Supplies 8.500 n/c Work Requested: Right rear outer wheel damaged, passenger door stuck open 60.00 Labor Right rear outer wheel damaged from accident, remove wheel and tire, swap rim with one off of downed vehicle # 414131. Used tire off of 414132 to match inner. Labor 110.00 Passenger door stuck open due to body damage, lower track and side panel bent in, all need replacement. Pull out track enough to get door to move, door is also bent and needs to be replaced. Will order parts. [Recommendations] PM due by 7/15/2023 or 99,993 miles to extend the life of your vehicle. FAI due by 3/31/2024 Current Estimate 178.50 178.50 Revisions 0.00 Org. Estimate 170.00 Labor: Parts: 8.50 SubTotal: 178.50 Tax: 0.00 Total: 178.50 Bal Due: \$178.50 [Payments -] Vehicle Received: 5/22/2023 Customer Number: 89 I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein

amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair

described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the