

**Job Site Repair LLC**  
 12015 Brockton Ln N  
 Maple Grove, MN. 55369  
 Phone: 763-428-8891 Fax: 866-454-6909

**INVOICE**

**225154**

**INVOICE**

Ref # : 420901

Printed Date: 12/11/2022

Work Completed: 12/09/2022

**RJH Delivery, Inc. - Ryan Husband**  
 8362 Tamarack Village  
 Woodbury, MN 55125  
 Cellular 949-338-2774

2019 Ford - F59 Stripped Chassis - Ford 6.8L 99Y F59 10 CYL  
 Lic # : YBX3053 Odometer In : 61062  
 Unit # : 420901  
 VIN # : 1F65F5KY9 **K0A13775**

Part Description	Qty	Sale	Ext	Labor Description	Ext
Job Supplies			1.380	Work Requested: Inspect lights	n/c
				Labor	27.50
				Inspect lights, wiggle test wiring to rear right turn signals, could not get to fail. All lights work properly after repairs.	
				<b>[ Recommendations ]</b>	
				FAI due by 6/30/2023	
				PM due by 1/16/2023 or 61,125 miles to extend the life of your vehicle.	

Org. Estimate 28.88 Revisions 0.00 Current Estimate 28.88

<b>Labor:</b>	<b>27.50</b>
<b>Parts:</b>	<b>1.38</b>
<b>SubTotal:</b>	<b>28.88</b>
<b>Tax:</b>	<b>0.00</b>
<b>Total:</b>	<b>28.88</b>
<b>Bal Due:</b>	<b>\$28.88</b>

[ Payments - ]

Vehicle Received: 12/9/2022

Customer Number : 47

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: [www.jobsiterepair.com](http://www.jobsiterepair.com)

Email Address: [jeff@jobsiterepair.com](mailto:jeff@jobsiterepair.com)