## Job Site Repair LLC

12015 Brockton Ln N Maple Grove, MN. 55369

Phone: 763-428-8891 Fax: 866-454-6909

INVOICE

231733

Odometer In: 56609

**INVOICE** Work Completed: 05/08/2023 Ref #: 420902 Printed Date: 05/10/2023

RJH Delivery, Inc. - Ryan Husband

2019 Ford - F59/F53 Stripped Chassis - Ford 6.8L 99Y F59 10 CYL

8362 Tamarack Village Woodbury, MN 55125 Lic #: YBX3054

Unit #: 420902

Cellular 949-338-2774		VIN #: 1F65F5KY7 <b>K0A13774</b>				
Part Description	Qty	Sale	Ext	Labor Description	Ext	
Hanger Bulkhead door	1.000	59.87	59.87	Work Requested: Bulkhead door hard to move	n/c	
Rivets 1/4	5.000	0.72	3.60	Labor	110.00	
Job Supplies			5.500	Inspect bulkhead door, replace worn out upper door track, rivet down loose lower track, lube and adjust door. Door works fine after repairs.		

[ Recommendations ]

PM due by 7/24/2023 or 58,397 miles to extend the life of your

vehicle.

FAI due by 5/31/2024

183.65 Revisions 0.00 Current Estimate 183.65 Org. Estimate

110.00 Labor: Parts: 68.97

SubTotal: Tax:

178.97 4.68 183.65

Total: Bal Due: \$183.65

[ Payments - ]

Vehicle Received: 5/8/2023 Customer Number: 47

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair

Visit us on the web: www.jobsiterepair.com

Email Address: jeff@jobsiterepair.com