Job Site Repair LLC

12015 Brockton Ln N Maple Grove, MN. 55369

Phone: 763-428-8891 Fax: 866-454-6909

INVOICE

231965

INVOICE Work Completed: 05/22/2023 Ref #: 422332 Printed Date: 05/23/2023

RJH Delivery, Inc. - Ryan Husband

2019 Ford - F59/F53 Stripped Chassis - Ford 6.8L 99Y F59 10 CYL

8362 Tamarack Village

Lic #: YBX3067

Unit #: 422332

Odometer In: 68347

Woodbury, MN 55125 Cellular 949-338-2774

VIN #: 1F66F5KY6 K0A11261

Part Description	Qty	Sale	Ext	Labor Description	Ext
Oil 10W30 Citgard 600	7.000	4.45	31.15	 Work Requested: PM, replace drivers side front tire	n/c
Filter Oil	1.000	12.28	12.28	PM Service	80.00
Light Amber LED	1.000	10.93	10.93	Change oil, oil filter, lube vehicle	
Brake pad	1.000	127.20	127.20	Labor	27.50
245/70/19.5 ZENNA AP250	1.000	263.49	263.49	Inspect lights, replace burnt out upper front left marker light. All	
Tire Disposal	1.000	15.00	15.00	lights work properly after repairs.	
Job Supplies			18.380	Labor During PM inspection found rear brake pads under 4 MM thick,	220.00
				replace pads.	
				Labor tire	40.00
				Replace drivers side steer tire and balance, air to 100 PSI	

[Recommendations]

FAI due by 7/31/2023

PM due by 9/22/2023 or 72,341 miles to extend the life of your

vehicle.

878.75 Revisions 0.00 Current Estimate 878.75 Org. Estimate

367.50 Labor: Parts: 463.43

Tire Fees:

15.000

SubTotal: Tax:

845.93 32.82

Total: Bal Due:

878.75 \$878.75

[Payments -]

Vehicle Received: 5/22/2023 Customer Number: 47

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair

Visit us on the web: www.jobsiterepair.com