

Job Site Repair LLC
 12015 Brockton Ln N
 Maple Grove, MN. 55369
 Phone: 763-428-8891 Fax: 866-454-6909

INVOICE

225491

INVOICE

Ref # : 422810

Printed Date: 01/01/2023

Work Completed: 12/30/2022

TEPA, Inc. - Tyrone Suhr
 3325 Skycroft Circle
 Minneapolis, MN 55418
 Cellular 612-202-6080

2019 Ford - F59 Stripped Chassis - Ford 6.8L 99Y F59 10 CYL
 Lic # : YBX6882 Odometer In : 65330
 Unit # : 422810
 VIN # : 1F66F5KYX **K0A16057**

Part Description	Qty	Sale	Ext	Labor Description	Ext
Oil 10W30 Citgard 600	7.500	4.22	31.65	Work Requested: PM	n/c
Filter oil	1.000	8.36	8.36	PM Service	80.00
Brake pads	2.000	76.83	153.66	Change oil, oil filter, lube vehicle	
Job Supplies			26.000	Labor	220.00
				During PM inspection found front brake pads under 2 MM thick, replace pads.	
				Labor	220.00
				During PM inspection found rear brake pads under 2 MM thick, replace pads.	
				[Recommendations]	
				PM due by 4/30/2023 or 69,330 miles to extend the life of your vehicle.	
				FAI due by 8/31/2023	

Org. Estimate 754.24 Revisions 0.00 Current Estimate 754.24

Labor:	520.00
Parts:	219.67
SubTotal:	739.67
Tax:	14.57
Total:	754.24
Bal Due:	\$754.24

[Payments -]

Vehicle Received: 12/30/2022

Customer Number : 80

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: www.jobsiterepair.com

Email Address: jeff@jobsiterepair.com