

**Job Site Repair LLC**  
12015 Brockton Ln N  
Maple Grove, MN. 55369  
Phone: 763-428-8891 Fax: 866-454-6909

**INVOICE**

**231958**

**INVOICE**

Ref # : 424167

Printed Date: 05/23/2023

Work Completed: 05/22/2023

**B Jackson Home Del. Inc - Bruce Jackson**

11331 Wildflower Drive N  
Lake Elmo, MN 55042  
Cellular 651-335-1167

2019 Ford - F59/F53 Stripped Chassis - Ford 6.8L 99Y F59 10 CYL

Lic # : YBX3090

Odometer In : 49907

Unit # : 424167

VIN # : 1F66F5KY1 K0A12320

Part Description	Qty	Sale	Ext	Labor Description	Ext
Job Supplies			7.880	Work Requested: Blower motor out	n/c
				Labor	157.50
				Inspect HVAC system, no blower on /C mode, trace wiring, found broken wire to A/C low pressure switch, repaired wiring. Clean out blower box. A/C blows at 65 degrees after repairs.	
				<b>[ Recommendations ]</b>	
				PM due by 8/25/2023 or 53,153 miles to extend the life of your vehicle.	
				FAI due by 8/31/2023	

Org. Estimate 165.38 Revisions 0.00 Current Estimate 165.38

<b>Labor:</b>	<b>157.50</b>
<b>Parts:</b>	<b>7.88</b>
<b>SubTotal:</b>	<b>165.38</b>
<b>Tax:</b>	<b>0.00</b>
<b>Total:</b>	<b>165.38</b>
<b>Bal Due:</b>	<b>\$165.38</b>

[ Payments - ]

Vehicle Received: 5/22/2023

Customer Number : 62

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: [www.jobsiterepair.com](http://www.jobsiterepair.com)

Email Address: [jeff@jobsiterepair.com](mailto:jeff@jobsiterepair.com)