

Job Site Repair LLC
 12015 Brockton Ln N
 Maple Grove, MN. 55369
 Phone: 763-428-8891 Fax: 866-454-6909

INVOICE

231609

INVOICE

Ref #: 424633

Printed Date: 04/28/2023

Work Completed: 04/27/2023

AZAL, Inc. - Ali Aldera
 7317 W Franklin Ave.
 St. Louis Park, MN 55426
 Office 612-803-1511 Ali Aldera
 Cellular 651-666-3354 Ryan Fritz

2019 Ford - F59 Stripped Chassis - Ford 6.8L 99Y F59 10 CYL
 Lic #: YBY2565 Odometer In : 82058
 Unit #: 424633
 VIN #: 1F66F5KY6 **K0A11017**

Part Description	Qty	Sale	Ext	Labor Description	Ext
Seal	1.000	73.34	73.34	Work Requested: Replace leaking radiator, broken	n/c
Pinion Nut	1.000	120.39	120.39	window latch and leaking pinion seal found at last PM	
Oil 75/90 Synthetic Oilmaster	1.000	8.54	8.54	Labor	220.00
Latch sliding window	1.000	63.92	63.92	Inspect for leaks by rear end, found pinion seal leaking, remove drive line, pinion seal, yoke and nut. Clean surfaces and	
Radiator	1.000	446.59	446.59	reassemble with new seal and pinion nut, fill fluid. Clean rear end	
Antifreeze Dex Cool	4.000	4.09	16.36	and inspect for leaks, none found.	
Job Supplies			23.380	Labor	27.50
				Replace broken drivers side window latch	
				Labor	220.00
				Drain coolant, remove hoses and clamps, remove radiator. Install new radiator and reassemble. Fill coolant and pressure test, no leaks visible after repairs.	
				[Recommendations]	
				PM due by 8/25/2023 or 85,908 miles to extend the life of your vehicle.	
				FAI due by 7/31/2023	

Org. Estimate 1,274.89 Revisions 0.00 Current Estimate 1,274.89

Labor:	467.50
Parts:	752.52
SubTotal:	1,220.02
Tax:	54.87
Total:	1,274.89
Bal Due:	\$1,274.89

[Payments -]

Vehicle Received: 4/27/2023

Customer Number : 4

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: www.jobsiterepair.com

Email Address: jeff@jobsiterepair.com