

Job Site Repair LLC
 12015 Brockton Ln N
 Maple Grove, MN. 55369
 Phone: 763-428-8891 Fax: 866-454-6909

INVOICE

231624

INVOICE

Ref # : 426272

Printed Date: 04/30/2023

Work Completed: 04/28/2023

VP Transport - Parth Lparel
 7161 Pleasant View Drive
 Saint Paul, MN 55112
 Cellular 651-206-8345

2019 Ford - F59/F53 Stripped Chassis - Ford 6.8L 99Y F59 10 CYL
 Lic # : YBY0992 Odometer In : 82003
 Unit # : 426272
 VIN # : 1F66F5KY1 **K0A11961**

Part Description	Qty	Sale	Ext	Labor Description	Ext
Gusset Spring Bumper RH	1.000	86.92	86.92	Work Requested: Repair damaged right rear corner	n/c
Corner Gusset	1.000	112.57	112.57	Labor	330.00
Sealant caulking	1.000	11.73	11.73	Remove rear bumper, springs and support plates. Straighten out bottom corner, install new support plates. Reassemble and seal. Paint affected area, replace reflector.	
Reflector Red 3 in round	1.000	3.00	3.00		
Job Supplies			16.500		

[Recommendations]

PM due by 7/20/2023 or 83,757 miles to extend the life of your vehicle.
 FAI due by 5/31/2023

Org. Estimate 576.84 Revisions 0.00 Current Estimate 576.84

Labor:	330.00
Parts:	230.72
SubTotal:	560.72
Tax:	16.12
Total:	576.84
Bal Due:	\$576.84

[Payments -]

Vehicle Received: 4/28/2023

Customer Number : 89

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: www.jobsiterepair.com

Email Address: jeff@jobsiterepair.com