

Job Site Repair LLC
 12015 Brockton Ln N
 Maple Grove, MN. 55369
 Phone: 763-428-8891 Fax: 866-454-6909

INVOICE

231950

INVOICE

Ref # : 432753

Printed Date: 05/22/2023

Work Completed: 05/19/2023

TEPA, Inc. - Tyrone Suhr
 3325 Skycroft Circle
 Minneapolis, MN 55418
 Cellular 612-202-6080

2020 Ford - F59 Stripped Chassis - Ford 7.3L 99N 8 CYL
 Lic # : YBZ2522 Odometer In : 59275
 Unit # : 432753
 VIN # : 1F66F5KN4 L0A03179

Part Description	Qty	Sale	Ext	Labor Description	Ext
Hose	4.000	2.69	10.76	Work Requested: Federal Annual Inspection	n/c
Hose clamp	2.000	1.02	2.04	Labor	110.00
Antifreeze Dex Cool	4.000	4.09	16.36	Noticed coolant leak, found hole rubbed through in overflow hose, replace hose and clamps, fill coolant. Pressure test with no leaks visible after repairs.	
Muffler clamp	1.000	11.67	11.67		
Job Supplies			11.130	Labor	27.50
				Exhaust turn down clamp missing, replace clamp.	
				Inspection	85.00
				Vehicle Inspection & PASSED after above repairs	
				[Recommendations]	
				PM due by 7/15/2023 or 59,790 miles to extend the life of your vehicle.	
				FAI due by 5/31/2024	

Org. Estimate 277.53 Revisions 0.00 Current Estimate 277.53

Labor:	222.50
Parts:	51.96
SubTotal:	274.46
Tax:	3.07
Total:	277.53
Bal Due:	\$277.53

[Payments -]

Vehicle Received: 5/19/2023

Customer Number : 80

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: www.jobsiterepair.com

Email Address: jeff@jobsiterepair.com