

**Job Site Repair LLC**  
 12015 Brockton Ln N  
 Maple Grove, MN. 55369  
 Phone: 763-428-8891 Fax: 866-454-6909

**INVOICE**

**231792**

**INVOICE**

Ref # : 434570

Printed Date: 05/12/2023

Work Completed: 05/11/2023

**Turn by Turn Deliveries, Inc. - Heith Glenna**

33159 Malmberg Road  
 Lindstrom, MN 55045  
 Cellular 651-208-3040

2020 Ford - F59 Stripped Chassis - Ford 7.3L 99N 8 CYL

Lic # : YBZ1999

Odometer In : 98454

Unit # : 434570

VIN # : 1F66F5KN2 L0A03133

Part Description	Qty	Sale	Ext	Labor Description	Ext
Job Supplies			2.750	Work Requested: RVS not working	n/c
				Labor	55.00
				Inspect RVS system, found no power to unit. Trace wiring found power wire broken, repair wire. RVS system works normally after repairs.	
				<b>[ Recommendations ]</b>	
				PM due by 8/25/2023 or 101,145 miles to extend the life of your vehicle.	
				FAI due by 5/31/2024	

Org. Estimate 57.75      Revisions 0.00      Current Estimate 57.75

<b>Labor:</b>	<b>55.00</b>
<b>Parts:</b>	<b>2.75</b>
<b>SubTotal:</b>	<b>57.75</b>
<b>Tax:</b>	<b>0.00</b>
<b>Total:</b>	<b>57.75</b>
<b>Bal Due:</b>	<b>\$57.75</b>

[ Payments - ]

Vehicle Received: 5/11/2023

Customer Number : 56

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: [www.jobsiterepair.com](http://www.jobsiterepair.com)

Email Address: [jeff@jobsiterepair.com](mailto:jeff@jobsiterepair.com)