## Job Site Repair LLC

12015 Brockton Ln N Maple Grove, MN. 55369

Phone: 763-428-8891 Fax: 866-454-6909

INVOICE

225329

**INVOICE** 

Ref #: 435120

Printed Date: 12/22/2022

Work Completed: 12/20/2022

Lake View Delivery, Inc. - Nathan Wegener 2812 Maryland Ave. S.

2013 Freightliner - Van Chassis - MT-55 - Cummins ISB6.7 CM2250 6 ( Lic #: YBY4084

Odometer In: 147390

Minneapolis, MN 55426

Unit #: 435120

			VIN # : 437AARDU6 <b>DCFJ5302</b>	
Qty	Sale	Ext		Ext
1.000	28.30	28.30	Work Requested: Inspect lights	n/c
1.000	154.32	154.32	Labor	55.00
Job Supplies	13.500	Inspect lights, replace faulty flasher relay. All lights work properly after repairs.		
			Diagnostics Engine/transmission/ABS/vehicle Diagnostics	50.00
			Labor  While returning vehicle CEL came on, scan for codes, crankcase pressure to high code present. Remove crankcase filter, found plugged. Replace filter and clear codes. No codes returning after repairs.	110.00
		Labor Low air flow from vents, remove blower assembly and clean out heater core, reassemble. Good air flow from vents now.  [Recommendations] FAI due by 6/30/2023 PM due by 3/9/2023 or 148,757 miles to extend the life of your vehicle.  Maintenance interval due 7/1/2022 to your vehicle.	55.00	
	1.000	1.000 28.30	1.000 28.30 28.30 1.000 154.32 154.32	Qty Sale Ext Labor Description  1.000 28.30 28.30 Work Requested: Inspect lights 1.000 154.32 154.32 Labor Inspect lights, replace faulty flasher relay. All lights work properly after repairs. Diagnostics Engine/transmission/ABS/vehicle Diagnostics Labor While returning vehicle CEL came on, scan for codes, crankcase pressure to high code present. Remove crankcase filter, found plugged. Replace filter and clear codes. No codes returning after repairs. Labor Low air flow from vents, remove blower assembly and clean out heater core, reassemble. Good air flow from vents now.  [ Recommendations ] FAI due by 6/30/2023 PM due by 3/9/2023 or 148,757 miles to extend the life of your vehicle.

Org. Estimate 479.86 Revisions 0.00 Current Estimate 479.86

270.00 Labor: Parts: 196.12

SubTotal: Tax:

466.12 13.74

Total: Bal Due: 479.86

\$479.86

[ Payments - ]

Vehicle Received: 12/20/2022

Customer Number: 79

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: www.jobsiterepair.com