

Job Site Repair LLC
 12015 Brockton Ln N
 Maple Grove, MN. 55369
 Phone: 763-428-8891 Fax: 866-454-6909

INVOICE

230662

INVOICE

Ref # : 436038

Printed Date: 02/24/2023

Work Completed: 02/16/2023

Ryker, Inc. - Ryan Husband
 8362 Tamarack Village
 Saint Paul, MN 55125
 Cellular 949-338-2774

2021 Ford - F59/F53 Stripped Chassis - Ford 7.3L 99N 8 CYL
 Lic # : YCA7352 Odometer In : 37925
 Unit # : 436038
 VIN # : 1F65F5KN1 M0A03024

Part Description	Qty	Sale	Ext	Labor Description	Ext
Oil 10W30 Citgard 600	8.500	4.22	35.87	Work Requested: PM	n/c
Filter oil	1.000	8.46	8.46	PM Service	80.00
W/wiper blade	2.000	10.53	21.06	Change oil, oil filter, lube vehicle	
Light Amber LED	1.000	10.93	10.93	Labor	27.50
Job Supplies			6.750	Replace worn wiper blades	
				Labor	27.50
				Inspect lights, replace burnt out left side hood marker light. All lights work properly after repairs.	
				[Recommendations]	
				PM due by 6/16/2023 or 41,925 miles to extend the life of your vehicle.	
				FAI due by 4/30/2023	

Org. Estimate 223.81 Revisions 0.00 Current Estimate 223.81

Labor:	135.00
Parts:	83.07
SubTotal:	218.07
Tax:	5.74
Total:	223.81
Bal Due:	\$223.81

[Payments -]

Vehicle Received: 2/16/2023

Customer Number : 78

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: www.jobsiterepair.com

Email Address: jeff@jobsiterepair.com