

Job Site Repair LLC
 12015 Brockton Ln N
 Maple Grove, MN. 55369
 Phone: 763-428-8891 Fax: 866-454-6909

INVOICE

231930

INVOICE

Ref # : 438115

Printed Date: 05/21/2023

Work Completed: 05/18/2023

VP Transport - Parth Lparel
 7161 Pleasant View Drive
 Saint Paul, MN 55112
 Cellular 651-206-8345

2012 Workhorse - W62 - General Motors 6.0L LY6 - Workhorse 8 CYL
 Lic # : YBZ4564 Odometer In : 102568
 Unit # : 438115
 VIN # : 5B4LFG2E4 **C3448568**

Part Description	Qty	Sale	Ext	Labor Description	Ext
Belt Serpentine	1.000	56.61	56.61	Work Requested: Tow in, serpentine belt broke.	n/c
Idler pulley	1.000	39.29	39.29	Labor	110.00
Tensioner pulley	1.000	88.79	88.79	Get vehicle into shop, serpentine belt broke from seized up tensioner pulley. Replace tensioner, failing idler pulley and serpentine belt.	
Switch Stoplite	1.000	23.80	23.80		
Job Supplies			9.630	Labor	82.50
				Electric brake booster not working, found and repaired shorted out wiring. Brake switch failed, replace switch. Brakes work correctly after repairs.	
				[Recommendations]	
				PM due by 9/11/2023 or 106,345 miles to extend the life of your vehicle.	
				FAI due by 8/31/2023	

Org. Estimate 426.31 Revisions 0.00 Current Estimate 426.31

Labor:	192.50
Parts:	218.12
SubTotal:	410.62
Tax:	15.69
Total:	426.31
Bal Due:	\$426.31

[Payments -]

Vehicle Received: 5/18/2023

Customer Number : 89

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: www.jobsiterepair.com

Email Address: jeff@jobsiterepair.com