

**Job Site Repair LLC**  
 12015 Brockton Ln N  
 Maple Grove, MN. 55369  
 Phone: 763-428-8891 Fax: 866-454-6909

**INVOICE**

**231880**

**INVOICE**

Ref # : 442555

Printed Date: 05/18/2023

Work Completed: 05/16/2023

**Ryker, Inc. - Ryan Husband**  
 8362 Tamarack Village  
 Saint Paul, MN 55125  
 Cellular 949-338-2774

2021 Ford - F59/F53 Stripped Chassis - Ford 7.3L 99N 8 CYL  
 Lic # : YBZ8748 Odometer In : 32841  
 Unit # : 442555  
 VIN # : 1F65F5KN9 M0A03031

Part Description	Qty	Sale	Ext	Labor Description	Ext
Large Triangle Window Gasketed	1.000	205.23	205.23	Work Requested: Passenger side corner window	n/c
Window Sealer	1.000	51.17	51.17	broken, replace plexiglass with glass.	
Windshield Molding	1.000	24.40	24.40	Labor	137.50
Job Supplies			6.880	Remove plexiglass from passenger corner window, clean frame and glue glass in its place. Install new window trim.	
<b>[ Recommendations ]</b>					
PM due by 8/21/2023 or 35,628 miles to extend the life of your vehicle.					
FAI due by 4/30/2024					

Org. Estimate 446.31      Revisions 0.00      Current Estimate 446.31

<b>Labor:</b>	<b>137.50</b>
<b>Parts:</b>	<b>287.68</b>
<b>SubTotal:</b>	<b>425.18</b>
<b>Tax:</b>	<b>21.13</b>
<b>Total:</b>	<b>446.31</b>
<b>Bal Due:</b>	<b>\$446.31</b>

[ Payments - ]

Vehicle Received: 5/16/2023

Customer Number : 78

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: [www.jobsiterepair.com](http://www.jobsiterepair.com)

Email Address: [jeff@jobsiterepair.com](mailto:jeff@jobsiterepair.com)