

Job Site Repair LLC
 12015 Brockton Ln N
 Maple Grove, MN. 55369
 Phone: 763-428-8891 Fax: 866-454-6909

INVOICE

231877

INVOICE

Ref # : 448525

Printed Date: 05/18/2023

Work Completed: 05/16/2023

Jet Delivers, Inc. - Jillian Helgerson

2870 Goldenrod Way
 Long Lake, MN 55356
 Cellular 651-442-2857

2021 Freightliner - Van Chassis - MT-45 - General Motors 6.0L L96 - Va
 Lic # : YCA2308 Odometer In : 81098
 Unit # : 448525
 VIN # : 4UZAC2GA0 MCMR0493

Part Description	Qty	Sale	Ext	Labor Description	Ext
Power Steering Pump	1.000	1,416.11	1,416.11	Work Requested: Replace rear tires, passenger door	n/c
LV Transmission Fluid	3.000	10.72	32.16	stuck, power steering pump leaking.	
Guide lower door	1.000	167.82	167.82	Labor	210.00
Mudflap Bracket	1.000	50.06	50.06	Drain power steering fluid, remove leaking power steering pump,	
225/70R/19.5 HMT Deep XT	4.000	198.65	794.60	swap fittings and pulley to new pump. Install new pump, fill fluid	
Tire Disposal	3.000	15.00	45.00	and bleed system. Wash off engine bay, no leaks visible after	
Job Supplies			21.750	repairs.	
				Labor	78.75
				Inspect passenger side door, found lower track worn out, replace	
				track, lube and adjust door. Door works fine now..	
				Labor	26.25
				Replace bent up rear left anti-sail bracket for mud flap.	
				Labor tire	120.00
				Replace drive tires, air to 100 PSI. Existing tires were at 3,3,5 &	
				10/32", saved 10/32" tire for run out use.	
				[Recommendations]	
				PM due by 9/8/2023 or 83,964 miles to extend the life of your	
				vehicle.	
				FAI due by 11/30/2023	

Org. Estimate 3,147.67 Revisions 0.00 Current Estimate 3,147.67

Labor:	435.00
Parts:	2,482.50
Tire Fees:	45.000
SubTotal:	2,962.50
Tax:	185.17
Total:	3,147.67
Bal Due:	\$3,147.67

[Payments -]

Vehicle Received: 5/16/2023

Customer Number : 64

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: www.jobsiterepair.com

Email Address: jeff@jobsiterepair.com