Job Site Repair LLC

12015 Brockton Ln N Maple Grove, MN. 55369

Phone: 763-428-8891 Fax: 866-454-6909

INVOICE

231753

INVOICE Work Completed: 05/09/2023 Ref #: 449997 Printed Date: 05/11/2023 2021 Freightliner - Van Chassis - MT-55 - General Motors 6.0L L96 - Va Fern, Inc. - Darla Fern 1325 200th Street Odometer In: 47937 Lic #: GD83575 Baldwin, WI 54002 Unit #: 449997 Cellular 612-812-6584 VIN #: 4UZAC3GA6 MCMP7785 **Part Description** Sale Qty Ext **Labor Description** Ext Job Supplies 1.380 Work Requested: Rear door inside handle broken. n/c Labor 27.50 Inspect rear door, bolt missing from inside release handle, install new bolt and lube lock. [Recommendations] PM due by 8/28/2023 or 51,457 miles to extend the life of your FAI due by 8/31/2023 28.88 Revisions 0.00 Current Estimate 28.88 27.50 Org. Estimate Labor: Parts: 1.38 SubTotal: 28.88 Tax: 0.00 Total: 28.88 Bal Due: \$28.88 [Payments -] Vehicle Received: 5/9/2023 Customer Number: 16

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the

amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair

Visit us on the web: www.jobsiterepair.com