

Job Site Repair LLC
 12015 Brockton Ln N
 Maple Grove, MN. 55369
 Phone: 763-428-8891 Fax: 866-454-6909

INVOICE

231786

INVOICE

Ref # : 451371

Printed Date: 05/11/2023

Work Completed: 05/10/2023

Ryker, Inc. - Ryan Husband
 8362 Tamarack Village
 Saint Paul, MN 55125
 Cellular 949-338-2774

2021 Ford - F59/F53 Stripped Chassis - Ford 7.3L 99N 8 CYL
 Lic # : YBZ8749 Odometer In : 31451
 Unit # : 451371
 VIN # : 1F65F5KN2 M0A03033

| Part Description | Qty | Sale | Ext | Labor Description | Ext |
|-----------------------|-------|-------|-------|---|-------|
| Oil 10W30 Citgard 600 | 8.500 | 4.45 | 37.83 | Work Requested: PM, straighten front bumper | n/c |
| Filter oil | 1.000 | 8.46 | 8.46 | PM Service | 80.00 |
| Antifreeze Dex Cool | 1.000 | 4.09 | 4.09 | Change oil, oil filter, lube vehicle | |
| W/ Washer Fluid | 1.000 | 3.39 | 3.39 | Labor | 27.50 |
| W/wiper blade | 2.000 | 10.53 | 21.06 | Replace worn wiper blades | |
| Job Supplies | | | 8.130 | Labor | 55.00 |
| | | | | Straighten bent up front bumper. | |

[Recommendations]

PM due by 9/10/2023 or 35,451 miles to extend the life of your vehicle.
 FAI due by 4/30/2024

Org. Estimate 251.09 Revisions 0.00 Current Estimate 251.09

| | |
|------------------|-----------------|
| Labor: | 162.50 |
| Parts: | 82.96 |
| SubTotal: | 245.46 |
| Tax: | 5.63 |
| Total: | 251.09 |
| Bal Due: | \$251.09 |

[Payments -]

Vehicle Received: 5/10/2023

Customer Number : 78

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: www.jobsiterepair.com

Email Address: jeff@jobsiterepair.com