

**Job Site Repair LLC**  
 12015 Brockton Ln N  
 Maple Grove, MN. 55369  
 Phone: 763-428-8891 Fax: 866-454-6909

**INVOICE**

**231977**

**INVOICE**

Ref # : 463494

Printed Date: 05/23/2023

Work Completed: **05/22/2023**

**Ryker, Inc. - Ryan Husband**  
 8362 Tamarack Village  
 Saint Paul, MN 55125  
 Cellular 949-338-2774

2021 Ford - F59/F53 Stripped Chassis - Ford 7.3L 99N 8 CYL  
 Lic # : YBZ8747 Odometer In : 43353  
 Unit # : 463494  
 VIN # : 1F65F5KN0 M0A03029

Part Description	Qty	Sale	Ext	Labor Description	Ext
Spark Plug	8.000	12.00	96.00	Work Requested: CEL is on	n/c
Plug Wire	8.000	28.00	224.00	Diagnostics	50.00
Light Amber LED	1.000	10.93	10.93	Engine/transmission/ABS/vehicle Diagnostics	
Job Supplies			14.880	Labor	220.00
				Scan for engine codes, multiple misfires present. Replace spark plugs and wires. Clear codes and road test, no warning lights returning after repairs.	
				Labor	27.50
				Inspect lights, replace burnt out left mid ship marker light. All lights work properly after repairs.	
				<b>[ Recommendations ]</b>	
				PM due by 9/19/2023 or 47,057 miles to extend the life of your vehicle.	
				FAI due by 4/30/2024	

Org. Estimate 668.21 Revisions 0.00 Current Estimate 668.21

<b>Labor:</b>	<b>297.50</b>
<b>Parts:</b>	<b>345.81</b>
<b>SubTotal:</b>	<b>643.31</b>
<b>Tax:</b>	<b>24.90</b>
<b>Total:</b>	<b>668.21</b>
<b>Bal Due:</b>	<b>\$668.21</b>

[ Payments - ]

Vehicle Received: 5/22/2023

Customer Number : 78

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: [www.jobsiterepair.com](http://www.jobsiterepair.com)

Email Address: [jeff@jobsiterepair.com](mailto:jeff@jobsiterepair.com)