

Job Site Repair LLC
 12015 Brockton Ln N
 Maple Grove, MN. 55369
 Phone: 763-428-8891 Fax: 866-454-6909

INVOICE

225243

INVOICE

Ref # : 464534

Printed Date: 12/17/2022

Work Completed: 12/15/2022

Ryker, Inc. - Ryan Husband
 8362 Tamarack Village
 Saint Paul, MN 55125
 Cellular 949-338-2774

2021 Ford - F59/F53 Stripped Chassis - Ford 7.3L 99N 8 CYL
 Lic # : YCA7351 Odometer In : 20765
 Unit # : 464534
 VIN # : 1F64F5KNX M0A02529

Part Description	Qty	Sale	Ext	Labor Description	Ext
Oil 10W30 Citgard 600	8.500	4.22	35.87	Work Requested: PM	n/c
Filter oil	1.000	8.36	8.36	PM Service	80.00
W/ Washer Fluid	1.000	3.50	3.50	Change oil, oil filter, lube vehicle	
Job Supplies			4.000		

[Recommendations]

PM due by 4/15/2023 or 24,765 miles to extend the life of your vehicle.
 FAI due by 4/30/2023

Org. Estimate 135.32 Revisions 0.00 Current Estimate 135.32

Labor:	80.00
Parts:	51.73
SubTotal:	131.73
Tax:	3.59
Total:	135.32
Bal Due:	\$135.32

[Payments -]

Vehicle Received: 12/15/2022

Customer Number : 78

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: www.jobsiterepair.com

Email Address: jeff@jobsiterepair.com