## Job Site Repair LLC

12015 Brockton Ln N Maple Grove, MN. 55369

Phone: 763-428-8891 Fax: 866-454-6909

INVOICE

231799

**INVOICE** Work Completed: 05/11/2023 Ref #: 470186 Printed Date: 05/12/2023

RJH Delivery, Inc. - Ryan Husband

2021 Ford - F59/F53 Stripped Chassis - Ford 7.3L 99N 8 CYL

8362 Tamarack Village

Lic #: YCA7381

Odometer In: 24193

Woodbury, MN 55125 Cellular 949-338-2774

Unit #: 470186

VIN #: 1F66F5KN0 M0A02855

Part Description	Qty	Sale	Ext	Labor Description	Ext
Oil 10W30 Citgard 600	8.000	4.45	35.60	Work Requested: Federal Annual Inspection	n/c
Filter Oil	1.000	12.28	12.28	PM Service	80.00
Filter Air	1.000	35.46	35.46	Change oil, oil filter, lube vehicle	
Light Amber LED	1.000	10.93	10.93	Labor	27.50
Job Supplies			9.630	Inspect lights, replace burnt out front upper far left marker light. All lights work properly after repairs.	
				Inspection	85.00

[ Recommendations ]

PM due by 9/11/2023 or 28,193 miles to extend the life of your vehicle.

Vehicle Inspection & PASSED after above repairs

FAI due by 5/31/2024

303.35 Revisions 0.00 Current Estimate 303.35 Org. Estimate

192.50 Labor: Parts: 103.90

SubTotal: Tax:

296.40 6.95 303.35

Total: Bal Due:

\$303.35

[ Payments - ]

Vehicle Received: 5/11/2023 Customer Number: 47

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair

Visit us on the web: www.jobsiterepair.com