

**Job Site Repair LLC**  
 12015 Brockton Ln N  
 Maple Grove, MN. 55369  
 Phone: 763-428-8891 Fax: 866-454-6909

**INVOICE**

**231602**

**INVOICE**

Ref # : 473777

Printed Date: 04/28/2023

Work Completed: 04/28/2023

**JJH Transport Corp. - Josh Hanson**  
 14355 Irish Ave. N.  
 Hugo, MN 55038  
 Cellular 651-558-1239

2021 Ford - F59/F53 Stripped Chassis - Ford 7.3L 99N 8 CYL  
 Lic # : YCC0276 Odometer In : 16593  
 Unit # : 473777  
 VIN # : 1F65F5KN4 M0A12364

Part Description	Qty	Sale	Ext	Labor Description	Ext
Fuse tap	1.000	8.25	8.25	Work Requested: 12 volt charging ports not working	n/c
Fuse	2.000	1.00	2.00	Labor	82.50
Power point outlet dual	1.000	10.12	10.12	Inspect charging ports, found power tap broken, run new power supply and install new twin 12 volt ports. Labor credit as discussed.	-2,500.00
				<b>[ Recommendations ]</b>	
				PM due by 1/14/2023 or 15,860 miles to extend the life of your vehicle.	
				FAI due by 10/31/2023	

Org. Estimate -2,395.63 Revisions 0.00 Current Estimate -2,395.63

<b>Labor:</b>	<b>-2,417.50</b>
<b>Parts:</b>	<b>20.37</b>
<b>SubTotal:</b>	<b>-2,397.13</b>
<b>Tax:</b>	<b>1.50</b>
<b>Total:</b>	<b>-2,395.63</b>
<b>Bal Due:</b>	<b>\$-2,395.63</b>

[ Payments - ]

Vehicle Received: 4/28/2023

Customer Number : 29

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: [www.jobsiterepair.com](http://www.jobsiterepair.com)

Email Address: [jeff@jobsiterepair.com](mailto:jeff@jobsiterepair.com)