

Job Site Repair LLC
 12015 Brockton Ln N
 Maple Grove, MN. 55369
 Phone: 763-428-8891 Fax: 866-454-6909

INVOICE

231724

INVOICE

Ref # : 475497

Printed Date: 05/10/2023

Work Completed: **05/05/2023**

Dilly Logistics, Inc. - Vandan Vekaria
 7008 92nd Ave. N.
 Brooklyn Park, MN 55445
 Cellular 651-410-4911

2021 Ford - F59/F53 Stripped Chassis - Ford 7.3L 99N 8 CYL
 Lic # : PLJ1950 Odometer In : 22066
 Unit # : 475497
 VIN # : 1F66F5KN6 **M0A16775**

Part Description	Qty	Sale	Ext	Labor Description	Ext
Job Supplies			2.750	Work Requested: RVS system not working correctly	n/c
				Labor	55.00
				Inspect RVS system, left camera dark on monitor, remove dash panel to access monitor. Found left camera unplugged secure connection. Tighten other monitor connections. RVS works fine after repairs.	
				[Recommendations]	
				PM due by 7/16/2023 or 24,141 miles to extend the life of your vehicle.	
				FAI due by 12/31/2023	

Org. Estimate 57.75 Revisions 0.00 Current Estimate 57.75

Labor:	55.00
Parts:	2.75
SubTotal:	57.75
Tax:	0.00
Total:	57.75
Bal Due:	\$57.75

[Payments -]

Vehicle Received: 5/5/2023

Customer Number : 92

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: www.jobsiterepair.com

Email Address: jeff@jobsiterepair.com